FITNESS CERTIFICATE

	(10 be mied	oy the	ASSI, Engineer)
1.	Name of the Officer		Gesetha. K.L
2.	Name of the School	1	Co-Operative Public School, theday
3	Location with name of Edn. Dist. Sub. Dist.	:	Kumaramangalam Edn. D181-Thos
4.	Classification of buildings as specified in column 4 of the application for fitness certificate and size	:	R.C.C Bowlding - 33 x 7-50m
5.	Period for which certificate is issued		2021-2022
6	Nature of defects if any		
	a) Foundation and basement	:	
	b) Superstructure		
	c) Doors and windows		None Under normal whether Coxclutions
	d) Wood work wrought and put up	:	Coxcletions
	e) Roof		
	f) Flooring		
	g) Miscellaneous (crecks etc.)	: _	
7.0	Any major defects noticed which will render the building unsafe in any manner		No Major dejects found
6	Whether the structure is sound or not for done properly		Yes
9.	Whether the structure is sound or not for conducting classes		The 81 sucture is sound under normal whether conditions
Not	e - 1) The stability of the structure shou intensity of wind, exposure to floor		xamined also with reference to location, altitude,
	Any addition observations if deeme with the certificate.	d nece	ssary for the certificate may be furnished separately
			e me on 26.10.21. If to conduct classes for the period of, academic
	2021-2022		
Plac	thodupusha s	ignatu	
Date	26.10.21)esign:	ASSISTANT ENGINEER
	Bonnon		OPERATIVE ALL
	5.200		13 To 2 hely uny
	JOHNSON MATHI	EW	PRESIDENT

THO SUN UZHA

THE BUPUZHA TALUK EBUCATIONAL CO-OPERATIVE SOCIETY LTB, No. 1-1+8 THORUPUZHA, IDUKKI DIST, KERALA

Principal Co-operative Public School

Thodupuzha